

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor 12 OCT 1925

VESSEL'S NAME *Stl S S COMBO*Rpt. *Bde*No. *3532*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*Docking.*

The Bordeaux surveyor reports the vessel placed in drydock and the bottom cleaned and coated

The following repairs have now been effected on account of wear & tear  
9 shell plates renewed, fore peak tank top stringer plate renewed on port side and minor repairs effected

It is submitted the vessel appears worthy to remain as classed with fresh record of survey Q. 25 Bde as recommended

100 A.I.

Q. 25 Bde.



© 2021

Lloyd's Register  
Foundation

*9.10.25*  
*[Signature]*