

Has shaft now been changed? No If so, state reasons

Is an approved appliance fitted at
009451-009458-0073


of "Harunasan Maru."

Kobe 5034

It is submitted the Kobe Surveyors should be requested to state, whether in their opinion the limit on the M.D. connecting rod can now be safely removed, in view of the rod being under special observation since August 1922 with satisfactory results.

Mr. H.M. 25

yes. See Kobe Ltr.
27/11/25



16/12/25

Lloyd's Register
Foundation

drilled at head of crack and 1" dia. fine thread C.I. plug fitted.