

14.10.01

Reference **S.**

Lloyd's Register of British and Foreign Shipping.
56, John Street, Sunderland.

16th. October, 1901.

The Secretary,
London,

RECORDED
LONDON.
REC'D 17 OCT 1901
ANS'D

Sir,

With reference to your remarks in the Classing letter of 15th. October, 1901. in connection with the 1st Entry Report No. 20718 of the S.S. "EDITH", I beg to state that the Poop, Bridge & Fore-castle Beams are Bulb angle as on the approved midship section. I regret having made this error.

With regard to the asphalt I might state that there is not any in the bottom, it is as stated on the 1st Entry Report " In bunkers and top of inner bottom under Boilers "

Your remarks regarding the Freeboard have been noted.

I am, Sir,

Your obedient Servant,

J. S. Shute



© 2020

Lloyd's Register Foundation

009451-009458-0076

should be "ft Cem ft Ash" in the Register Book. They should be reminded that the freeboard is a condition of the vessel's class, but on their report they state "without freeboard as condition of class"

710
tee.
he
to
sc
he
and
ds.
he

J. H.
11/10/01
any
if the
ne rec

Referred to the Chief Ship Surveyor.

[Handwritten signature]

17 OCT. 1901

50156 for Mr. Hill to note.

*Noted
J.H.T.
17/10/01
@ H.P.*

101, 100, 100, 100



© 2020

Lloyd's Register
Foundation

*inwards of
the
the
the*

Received
SEL'S
The Rai
(T)