

Received from Chief Surveyors.....

to Chief Surveyors.....

VESSEL'S NAME CORVINA REPORT Lon. No. 115254AFor the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Duration of Survey..... When due.....

The Owners of this vessel, in a letter to the BUENOS AIRES Surveyors, state that "as the steamer CORVINA has been put in the fishing service, at the moment we are not interested in the inspections".

The Buenos Aires Surveyors accordingly recommend the vessel's class be withdrawn.

It is submitted the vessel's class be withdrawn from the Register Book and three dots, with date underneath, be inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class
and insert (....)
8,47



© 2020

Lloyd's Register
Foundation

B.S. Due
10,46.

29-11-17
J. Mac,
2-9-17

J. Mac