

COPY.

19th April, 1907.

I have to acquaint you that it appears from the Glasgow
st entry report on the machinery of the new Steamer
"RATHGYLE" that when the vessel was on her trial trip one
the condenser tube plates was found to be defective and
porary repairs were carried out to enable her to proceed to
men, where it is stated a new tube plate is to be fitted.
I shall therefore be glad if you will arrange to give the
the necessary attention and forward your report to this
Office in due course.

I am, Sir,

Your obedient Servant,

Secretary.

H.T.Thomsen Esq.,

BREMERHAVEN.



© 2020

Lloyd's Register
Foundation

009469-009480-0095