

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18th June 1919 When handed in at Local Office 101 Port of Singapore
No. in Reg. Book. Survey held at Singapore Date, First Survey and Last Survey 15th June 1919
7/8 31225 on the Wood, Iron or Steel S. S. "Amur Maru" (No. of Visits One) Master

TONNAGE:-
GROSS 7770
UNDER DECK 7329
NET 4823
Built at Osaka By whom Osaka Iron Works When 1919
Owners Osaka Shosen Kaisha Port belonging to Osaka
Owners' Address
(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Destined Voyage
WB=CellDBorDBa feet; uE&B feet; f feet; f
total capacity tons. FPT tons; APT tons; MT feet tons.
N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.
Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER.
* for Special Survey.
Date of last Survey and of Periodical Surveys.
Years Assured now expired.
Machinery and Boiler Surveys (including date of N.B., if any).
First entry not yet received

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR
Vessel examined afloat.
One rivet found defective in the forward space of No 7 Ballast tank top in way of the Port side Tunnel.
A temporary repair has been effected by fitting a bolt.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Ornamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder	Caulking ditto	Sails
Rivets	Steering gear and its connections	Treenails ditto	Equipment letter
Breasthooks & Crutches	Windlass	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	„ length size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	„ Rule length size
Floors		Stringers, Clamps & Shells ditto	Hawser & Warps
Keelsons		Salting ditto	Standing & Running Rigging
		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 1,15,” or “to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c.”
It is recommended this vessel be retained as classed subject to the rivet being renewed at a convenient opportunity.

Survey Fee (per Section 29) £	Fees applied for, 19
Special Damage or Repair Fee (if any) (per Sec. 29) \$40	Received by me, 19
Travelling Expenses (if chargeable) £	
Second Surveyor's Fee (if any) £	

Committee's Minute
Character Assigned
See Minute on
Kobe 78. Rpt 25-4-4
Surveyor to Lloyd's Register of Shipping.
FRI. AUG. 29. 1919
TUE. APR. 27 1920
FRI. MAY. 7 1920
FRI. MAY. 14 1920