

20 MAY 1941 2

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *CANBERRA MARU.*Rpt. *Kob.* No. *11645*

Marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/32.

Survey *1st* S.S. No. *1* due *6.40*

1st S.S. No. *1* has now been held, and the following repairs

Vessel placed in dry dock
Bottom coated

Minor repairs effected.

submitted the vessel is worthy to remain as classed, with record
by *10.40* and notation of S.S. *N°1-40*

100 A1
With Freeboard
10.40 Kob.
S.S. Kob. N°1-40

externally only
11.41
© 2020
Lloyd's Register
Foundation
14.5.41

Surveyors should be informed *after* it is concluded
works in way of tunnel *have* been examined and tested but
may should be requested to state if this is so