

31 MAR 1937

2

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

TA AN.

Rpt. Kot.

No. 9962

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

2nd S.S. No. 1 (due 10.36)

The 2nd S.S. No. 1 has now been held, and the following repairs

done due to wear and tear:-

Vessel placed in dry dock.

Bottom coated.

Renewals to plating of After peak tank top and to No 3 double bottom tank top, floors and intercostals in way of same.

92 hatch boards and some rigging renewed and minor repairs carried out.

It is submitted the vessel is worthy to remain as classed, with record of Survey 2.37 and notation of S.S. No 1-37 as recommended.

100 A1

2.37 Osa

S.S. Osa No 1-37



© 2020
20.3.37

Lloyd's Register
Foundation

009493-009504-0311