

Lloyd's Register of Shipping

ROOM 208 LAKE OF THE WOODS BLDG.

MONTREAL... December... 28th... 1921.

LLOYD'S REGISTER,
LONDON.

REC'D
JAN 9 1922
NSD
B

The Secretary.
London.

Dear Sir. (S)

In reply to your letter of the 16th. inst.

I was under the impression that I had replied to your letter of the 17th of June last. But as I cannot find the record the fault is mine.

Montreal Rept. 1896. "CANADIAN LEADER" The rivetting of the bridge side plating is in accordance with the rules.

Depth from the top of the floors to the upper deck beams 28ft 6in.

" " " " " 2nd. " " 20ft 7in. ?

Moulded depth to the bridge deck 39ft 1 1/4 in.

Yours very truly.

H. J. Alderson



© 2020

Lloyd's Register
Foundation

009493-009504-0308

Referred to the Chief Ship Surveyor.

JAM

-9 JAN 1922

also for Mr. S. A. Hill to note.

It is concluded the height of the three decks is as shown in
 the plan of the ship but the Surveyors should be requested
 to State if this is so

blasing the
 of the :-
 13/1/22.

M. H. 11/1/22



© 2020
 Lloyd's Register
 Foundation