

Sent to Chief Surveyors 1. 11. 26

Received from Chief Surveyors

17 NOV 1926

VESSEL'S NAME

Stl. 8/K. Juan Mari

Report

BboNo. 6856

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

2nd No.

1

SURVEY PARTLY HELD.

When due

8. 25

When proposed to be completed

Portion of Survey held, &c.,

B. S. held 3. 26

The 2nd s.s. No. 1 due 8-25 has been partly held by the examination of the bottom and rudder in dry dock and of the fore hold, fore and after peaks, machinery space, decks, ^{masts,} ~~examination of~~ rigging, general equipment, hatches, windlass, steering gear and connections, and the testing of the forward tank in way of the fore hold.

2 shell plates on starboard side ~~forward~~ require to be renewed at the first opportunity.

The Bilbao Surveyors now state they have been informed by the Owners they propose to complete the survey in December next.

The year of grace expired 8-26.

It is submitted for the consideration of the Committee whether action might not be deferred.

? Have sea cocks & valves been seen?

See end of report Bbo 6856.

W. S. 11/12



© 2021

Lloyd's Register
Foundation

004505-004513-0075