

26 JUL 4E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"MONTCALM"

Rpt.

Lon.

No. 107624

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

The Surveyor reports cracks in the main stop valve chest of the No.5 boiler.

This boiler has been put out of action and the steam pipes blanked off pending the fitting of a new stop valve chest.

The Surveyor recommends No.5 boiler be not used again until main stop valve chest has been renewed.

It is submitted the vessel is eligible to remain as classed without fresh record of survey, subject as recommended.



25.7.39 © 2021

Lloyd's Register
Foundation

009522-009526-0082