

5c.11.26.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Stl. s.s.

"KARAKARA".

Rpt.

Syd.

No 955Z

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The class of this vessel is subject to damage to belting etc., through heavy weather being permanently repaired at a convenient opportunity.

The Sydney Surveyors now report the vessel examined on a pontoon, bottom recoated and damage through heavy weather repaired as necessary.

The Owners now state that as the vessel is on Ferry service in Sydney Harbour and under constant supervision, they desire the class to be withdrawn.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu indicating withdrawal of class at the Owners' request.

Withdraw class.

Insert ...

15.1.27.



© 2021

Lloyd's Register
Foundation

009535-009543-009544