

Chief Surveyors 26. 8. 25

Received from Chief Surveyors AUG 1925

S NAME S. K. Washington Report Lon No. 89223^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

Boiler

When due

5. 25.

Screw shaft due 6. 25.

The boiler survey became due in 5. 25. no part has been held.

A limit to examine the screw shaft before the end of June 1925. has expired.

The Owners now state that they have decided to withdraw the vessels class.

It is submitted that the vessels class be withdrawn from the Register Book & three dots inserted in lieu thereof. indicating that the class has been withdrawn at the request of the Owners.

Withdraw class.
Insert....

CMS JWD
26/8/25.
R

PM



© 2020

Lloyd's Register
Foundation

004557-004569-0114