

"BALAENA"

Sou. 18854

Before this case receives consideration
IT IS SUBMITTED the Southampton Surveyors be requested to
state the reasons for the bone and blubber press boiler
safety valves being adjusted to 60 lbs. as the approved
pressure is 70 lbs. The attached memo^s is forwarded for
their information and should be returned together with
their remarks. *OS's rpt 5965 is also enclosed. & should also be returned*

x Mr. Wang

In addition to the completion and test
of the factory electrical equipment the Surveyor states
that several small items remain to be completed. They
should be requested to detail the outstanding machinery
items in order that the full information is available
here.

See Sm. letter
18.11.46.

The Belfast Surveyors should confirm
the heating surface of the superheaters. The information
as per attached report from Newcastle (which should be re-
turned after perusal) shows 4,550 sq. ft. Their remarks
are awaited.

See Bel
letter 19/11/46

J Rus

13. 11. 46.



© 2020

Lloyd's Register
Foundation

004557-009569-0207