

-5 DEC 1941

y Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

'S NAME HAKUSIKA MARU Rpt. Smk No. 2932

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey CONDITION


The SHIMONOSEKI Surveyor reports (3.41) the vessel afloat and on account of local wastage a bolted doubling plate fitted to shell plate No. 2 in 7th strake below sheer (p & s).

The Surveyor recommends these bolted doubling plates be riveted at the first opportunity.

It is submitted the vessel is worthy to remain as classed without record of survey, subject as recommended.

As Now, Subject, etc.

Note The 2nd S.S. No. 3 has since become due (10.41)



009580-009589-0098

Japan.