

DECLASSIFIED  
SECTION

326

2

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME

HANKOW MARU

Rpt. Kob.

No. 11611

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

2<sup>nd</sup> S.S. No. 2

due 3,40

The 2<sup>nd</sup> S.S. No. 2 has now been held, and the following repairs

done:-

75 fathoms of worn chain cable & 8 shell plates renewed,  
repairs effected to deck plating, tank top plating & gunwales etc.

Vessel placed in dry dock, bottom coated.

It is submitted the vessel is worthy to remain as classed, with record  
of Survey 9,40 and notation of S.S. No 2-40

100 A.1.

Awwning dk. with freeboard

9,40 Kob

S.S. Kob. No 2-40

AS  
9/1/41



© 2021

Lloyd's Register  
Foundation