

E8 JUN 1950

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME STANVAC WELLINGTON REPORT S. Fo. No. 9513.For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey Docking. When due.....Noted.

Subject to outstanding repairs being dealt with by the Special Survey.

CBM
4.6.50.

and
C.S.S. Records: Defect
to note, fracturing & buckling
of stanchion plates also stays.

Noted. John

20-7-50

Lloyd's Register
Foundation

Tanks been tested? Yes | Doubling Plates under Sounding Pipes GOOD | (State if examined.)

| Sails

009610-009620-0123