

Received by Chief Ship Surveyor 22/2/11

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. S. Wallington Rpt. Emo No. 7092

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First entry

It is submitted the Limasly Surveyors should be requested to state whether they did not consider it necessary to examine the vessel inside, in view of their statement that the bottom on the port side is set up $\frac{3}{4}$ " over a length of 3 plates.

Dr. Emo. 23/2/11.
P.C. H.L.
~~Amo.~~

AM RBA
23/2/11



© 2021

Lloyd's Register Foundation

009621-009630-0197

Stenings	Ceiling	Hatches	Condition, how ascertained
	Cement or Asphalt		(State if necessary)