

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report..... 19..... When handed in at Local Office..... 21/2/11..... Port of..... GRIMSBY

No. in Reg. Book..... Survey held at..... GRIMSBY..... Date, First Survey..... and Last Survey..... 17/2/1911..... (No. of Visits..... one.....) Master.....

20 SUP on the Wood, Iron or Steel S. H. WALLINGTON
TONNAGE:- Built at Selby By whom Cochrane & Sons. When 1911
GROSS 300 Owners Premier Steam Fishing Co. Ltd. Port belonging to Grimsby
UNDER DEK. Owners' Address
NET (if not already recorded in Appendix to Register Book).

Surveyed ~~At~~ in Dry Dock? Name of Dock Fish dry Destined Voyage Fishing.
WB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port
100A1
Stm Yawler

(CLASS CONTEMPLATED)
Society's Freeboard (if assigned) as painted on Ship and now verified } ft..... ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking
Examined vessel in drydock found bottom slightly set up in launching on port side (about 3/4" over a length of 3 plates in a fore aft direction). This damage was considered of such slight account, that in my opinion it might be allowed to remain. The managing owner concurred in my opinion.

Survey made at the request the request of the managing owner & builder who were present.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Fell.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month..... Year.....
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt (state which.)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Butter Survey confined to the above	Caulking ditto	Sails
Rivets	Steering gear and its connections	Treenails ditto	Equipment letter
Breasthooks & Crutches	Windlass	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	length..... size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	(on board)
Floors		Stringers, Clamps & Shelves ditto	Rule length..... size
Keelsons		Salting ditto	(per Table 22)
		(State if examined.)	Hawser & Warps
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,09," or "to remain as classed and to have record of survey, 1,09, and the notations of ss No. 1-09 and ptND09, &c."

This report is forwarded for the information of the Committee

Survey Fee (per Section 28)	£	Fees applied for,	19.....
Special Damage or Repair Fee (if any) (per Sec. 28)	£	Received by me,	19.....
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute
Character Assigned

TUE. 28 FEB 1911
See minute on F.B. report.

W. R. M. Aspinall
Surveyor to Lloyd's Register of British & Foreign Shipping.

