

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME ST. S. M.V. "ARDOR" Rpt. Sen No. 9975


The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 90.5 Depth "d" ✓  
 Framing: Table No. ✓ Description Longitudinal framing  
 Longitudinal No. 42498  
 Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{\quad}{\quad} = \frac{\quad}{\quad}$  13.23  
 Deck Sheerstrake as approved  
Old Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✱ 100 A.1. (Steel) "Shelter dk with freeboard," as recommended. "Carrying Petroleum in Bulk" The Summer freeboard of 9ft 9in from centre of disc to top of statutory deck line at shelter deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

1 Dk (Stl) + Shelter Dk (Stl) + web frames. Longitudinal framing  
Cell D.B. E 69' 132t, D.T. + 36' 28it, F.P.T. 188t, A.P.T. 106t.  
FK 18 B.H (13 to upper Dk), pt Cen. Hays A. CP  
B 34, F 40. machy aft.



© 2021

Lloyd's Register Foundation

*[Handwritten signature]*  
 7.8.27