

from Repairs and should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report

Dkg.
SS.

2/60
1/58

8th June, 1961.

Dear Sirs,

SHELT CLASS VESSELS

I acknowledge receipt of your letter of the 29th May, and confirm that the ships listed by you can be dealt with on the engine Survey basis in accordance with the same arrangement as that approved in the case of the "SEDIH".

Yours faithfully,

Deputy Clerk to the
Classification Committee

The Surveyors,
SINGAPORE.



© 2020

Lloyd's Register
Foundation

009674-009681-0063

009674-009681-0064