

RAMS: SURVEYOR.



Lloyd's Register of Shipping,

BY AIRMAIL.

2, Laidlaw Building,

Battery Road,

(P.O. Box 480),

JW/YKN

RECEIVED

- 7 JUN 1950

Singapore, 2nd June, 1950.

Reference

"S"

Dear Sir,

Sumpitan C¹⁸/₁₆ CT 528

We have today received your circular letters, addressed to the Owners and dated 4th May, 1950, regarding the anchor and chain cable equipment of the vessels "SENAI" and "SUMPITAN".

Before forwarding these letters to the Owners of the vessels, the Straits Steamship Co. Ltd., we think it advisable to refer you to your letter of the 3rd February, 1950 and to other relevant correspondence regarding the equipment of the "SENAI".

In the final paragraph of this letter, we were asked to inform the Owners that the equipment of anchors and chain cables on board the "SENAI" and sister ships should be as that originally approved, particulars of which are given below.

2 bowers at $11\frac{1}{4}$ cwt. stockless

1 stream at $4\frac{3}{4}$ cwt. ex stock

165 fathoms of 1.2/16 stud chain cable.

According to records available in this office, both vessels have the equipment stated above and, in these circumstances, we have retained the two circular letters in this office pending receipt of your further instructions as to what action should now be taken.

Yours faithfully,

FOR THE SURVEYORS.

The Secretary,
L O N D O N.



Lloyd's Register
Foundation

009674-009681-0074

