

for this purpose, and why they were declined

image report made by anyone else? If so, by whom?

2 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

SENAI

REPORT

SNG

No. 7966


Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

COMPLETION OF SPECIAL SURVEY OF ENGINES ~~AND BOILERS FOR S.S. No.~~

This Survey, due 6.49 ~~new~~ partly held 2.49 now completed, and the following repairs carried out (due to wear ~~tear~~) :-

General service pump replaced by spare.



© 2020

It is submitted the vessel is eligible to remain as classed, with
tation of MB5* 2.49 as recommended

Lloyd's Register
Foundation

009674-009681-0092

20.12.49

(General service pump was replaced with spare reconditioned unit at this time)