



9

2867

made secure in place. Navigating light circuits made good and tested. 2 new batteries supplied for lighting system. On completion fo repairs the main and auxiliary machinery examined under working conditions. Broken springs of inlet & exhaust valves renewed and spares supplied.

G. J. Huxford.



© 2020

Lloyd's Register  
Foundation