



# Lloyd's Register of British & Foreign Shipping,

Maritime Buildings, East Dock Street,

Dundee, 14<sup>th</sup> January 1911.

LLOYDS REGISTER,  
LONDON.

REC'D 16 JAN 1911

ANS'D

Reference

S

Sir

In reply to your letter of the 13<sup>th</sup> instant regarding the case of the S.S. London Queen, we beg to inform you that the number of rivets dealt with in the Engine Seating was 956, of which 585 were renewed and 371 hardened up as stated in our letter of the 7<sup>th</sup> instant; all these (956) rivets had been found more or less defective.

The rest of the rivets in the Seating were tested and found to be sound and therefore were not dealt with.

We are Sir,

Your obedient servants  
The Surveyors.

R. M. Salmon.

The Secretary.  
London.

Matthew Blackwood

009702-009710-0040

009702-009710-0048



Referred to the Chief Ship Surveyor.

al  
+ for Mr. Wayne  
to note

JAN. 13 1911



© 2020

Lloyd's Register  
Foundation