



Lloyd's Register of British & Foreign Shipping, im

Maritime Buildings, East Dock Street, t,

Dundee, 11<sup>th</sup> January 1911 711

LLOYDS REGISTER,  
LONDON.

RECEIVED 12 JAN 1911

ANSW 13

reference  
Sir.

In reply to your letter of 10<sup>th</sup> inst. regarding the riveting of the Engine seat in the S.S. London Queen. We beg to state that the whole of the riveting was tested, and that the number of rivets found defective, and more or less slack was 956, and those were renewed or hardened up as found necessary.

We are, Sir.

Your obedient servants.

The Surveyors.

per. M. Blackwood.

The Secretary.  
London.



© 2020

Lloyd's Register  
Foundation

009702-009710-0042

009702-009710-0048

Referred to the Chief ~~Supt~~ Surveyor.

JAN 12 1911

Also for Mr. S. A. Hill to note.

The number of rivets mentioned by Mr. Blackwood in this letter corresponds exactly with the number mentioned in his letter of 7<sup>th</sup> inst which would appear from the letter was that of all the rivets dealt with in rebuilding and re-riveting the engine seating. Mr. Salmon showed ~~that~~ <sup>it is submitted</sup> ~~that~~ <sup>you with Mr. Blackwood</sup> ~~that~~ <sup>all the rivets in the engine seating</sup> ~~that~~ <sup>about how many rivets had to be removed</sup> ~~and if not, to state how many rivets had to be removed~~ <sup>in rebuilding the seating</sup>

13/11

A.B.



© 2020

Lloyd's Register  
Foundation