

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

6th January, 1911.

Gentlemen,

S. With reference to Mr. Blackwood's report No. 7567 on the new steamer "LONDON QUEEN", I have to request that he will be good enough to state specifically how many rivets he found defective in the engine seating of this vessel.

Mr. Blackwood should at the same time state in detail what were the other defects (if any) which led <sup>to</sup> the engine seating being re-built and re-riveted.

I am, Gentlemen,

Your obedient servant,

Secretary

The Surveyors,

D U N D E E.



© 2020

Lloyd's Register  
Foundation

009702-009710-0045