

Submitted the Rotterdam Surgeons  
 should be requested to state whether they  
 examined and tested the puncture of this  
 engine seating after the puncture was  
 completed and whether the riveting of the vessel  
 generally was tested by them.

*L.* - *E. L. L.*  
30.12.10  
31/12/10.



© 2020

Lloyd's Register  
 Foundation

009702-009710-0052

present, and found that the holes for the various thicknesses came