

COPY.

Lloyd's Register of British & Foreign Shipping.

71, Fenchurch Street, E.C.

16th December, 1910.

Gentlemen

With reference to your first entry machinery report No.6569 in the case of the Steamer "LONDON QUEEN", I have to acquaint you that the Society's Surveyors at Rotterdam state in reply to inquiry that no sea connections were fitted in the Shipyard, and that they understood the vessel would be placed in dry dock for the machinery work on her arrival in this Country.

I have therefore to request that you will state, if you are in a position to do so, whether the blow off cocks are fitted with a spigot and brass covering plate and also give the dates of examination of completion of fitting of sea connections.

I am, Gentlemen,

Your obedient Servant,

The Surveyors,

MIDDLESBROUGH.



© 2020  
Secretary.

Lloyd's Register  
Foundation

009702- 009710- 0074