

3 MAR 1947

"HELGA MOLLER"

A 3rd S.S. No. 2, due 5.43, has not been held.

This ship has an "Examined" record of "8.46" (6 mos.).

The class is subject to keel and bottom plating etc. and to lower four rudder pintles being specially examined at the next dry docking, to indented shell plate E.4 (s.s) and shell plating etc. (p.s) being dealt with and to cargo battens being fitted at the first opportunity, to a further General Examination and necessary repairs being carried out by 2.47, and to (30 fathoms of chain cable being supplied).

A cablegram has been received 3.3.47 from the SHANGHAI Surveyor advising ship examined for damage and repairs effected. He also reports General Examination with repairs now due not dealt with but Owners state same will be attended to on ship's return from present voyage to Chingwantao. He asks for instructions.

It is submitted the Surveyor be informed (by cablegram) that the General Examination might be deferred pending ship's return from present voyage to Chingwantao provided he is satisfied with the present condition as now seen and as examined 8.46.

*Cab Shi:—*



© 2020

Lloyd's Register  
Foundation

009702- 009710 - 0166