

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in the

"INNESMOOR"

Sta. Rpt. 29736

It is submitted that
this vessel is eligible for
THE RECORD + LMC. 5.28 C-L.

Gil Engines 3 cy 21 $\frac{1}{4}$ " - 85" 2 S.C.S.A.

NHP. ^{417.}~~40~~ @

2DB. 120 lb.

William Doxford & Sons Ltd.

Std.

© 2020



@
24/5/25

Lloyd's Register
Foundation

009702-009710-0322

led from easily accessible mud-boxes, placed above the level of the working floor, with straight tail pipes to the barges