

Im.10.33.

31 NOV 1941

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME HITERU MARU Rpt. Kob No. 11863

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey _____

The KOBE Surveyors report (5.41) the vessel placed in dry dock, bottom coated, and on account of damage through stranding and subsequent salvage operations, 145 shell plates renewed, 27 faired, renewals or repairs to framing, floors, inner bottom, decks, bulkheads, double bottom etc. effected. *Sil*

A S.S. No. 1, due 3.42 (vessel 32 years old) has been partly held by the internal examination and testing of all double bottom tanks and fore and after peak tanks.

A General examination made

March next.

It is stated the Survey will be completed in

It is submitted the vessel appears worthy to remain as classed with record of survey 5.41.

100A1

Awning dk with fbd
5.41 Kob

PLATING to be DRILLED when vessel is 24 years old, or at next Special Survey thereafter.



© 2021

Lloyd's Register
Foundation

[Signature]

4.11.41

S.S. PART FIELD

6047210047240032