

11
16 MAY 1941

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SHIP'S NAME HOKKO MARU Rpt. Kob. No. 11756

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey _____

The Kobe Surveyors report this vessel placed in dry dock, bottom cleaned and coated, ~~repairs to~~ 3 Shell plates renewed repairs to framing and poop deck and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 3.41 as recommended.

100A1
3.41 Kob.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

© 2021

Lloyd's Register Foundation

009721-004724-0094