




TELEGRAMS: "REGISTER" KOBE
TELEPHONE: 2530 SANNOMIYA

LLOYD'S REGISTER OF SHIPPING

MEIKAI BUILDING

No. 32, AKASHI MACHI,

KOBE, November 19th 1937.-



The Secretary,
LONDON

"HINCHIK" ----- Kobe Report No.10268.
"SACHALIN SNAB" ----- Kobe Report No.10269.

Dear Sir,

In reply to your Classing Letter of the 26th October, I have to say that the compasses have been adjusted with and without the electric installation at full power, and the effects of switching on and off circuits, motors and other electro-magnetic apparatus within the vicinity of the compasses have been noted and found to be nil.

The moving parts of the switches are not alive in the "off" position.

Regretting that these matters were not made clear in my report,

I am, Dear Sir,

Yours faithfully,

C. Macpherson



© 2021

Lloyd's Register
Foundation

004721-004724-0116

Referred to Mr. Hill

- 6 DEC 1937

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED

DATE 12-08-2001 BY SP-1

REPORT

Regarding that these matters were not made clear in the

"LLOYD'S REGISTER"

The moving parties of the matters are not alive in the
and found to be null.

admission within the vicinity of the companies have been noted
emitting on and off airplanes, motors and other aircraft-mechanics
the aircraft in the vicinity of the tower, and the aircraft of
have to say that the companies have been admitted with and without
In regard to the aircraft of the 25th October.

DEPT. 271

"LLOYD'S REGISTER"
"LLOYD'S REGISTER" NO. 10000
"LLOYD'S REGISTER" NO. 10000

LONDON

REGISTERED

LONDON

RECEIVED
LLOYD'S REGISTER
LONDON



© 2021
Lloyd's Register
Foundation

- 1501 1401 1301 1201

1000 1000 1000 1000

1000 1000 1000 1000

1000 1000 1000 1000