

Received by Chief Ship Surveyor 30.8.01

Received from Chief Ship Surveyor

VESSEL'S NAME See S.S. "Oakley"Report Hpl. No. 11636

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>3/20"</u>	<u>Proportion</u>
Spar Sheerstrake . .	<u>✓</u>	<u>✓</u>
Description of Framing:— <u>Deep framing.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed † 100 A 1 ("Steel") as recommended.

† 100 A 1 ("Steel")1 DR (Im) 2 to B, deep framing & web frames. 3 DR Rule.N. B = Cell DB a & u E 183' f 144' 912 L APT 716FK 6BH Cam A & CP P 28' B 88' F 31'C. H. J.
30/8/01

© 2021

Lloyd's Register
Foundation

009743-009756-0077