

3m.0.20.

18 FEB 1921

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Wood Sc.Drifter "FLAME". Rpt. Dun. No 293

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Dundee Surveyors report that repairs have been effected to the centre and starboard side keelsons in way of the fish hold.

It is submitted the vessel appears worthy to remain as classed without record of survey.

17. 2. 21.

It should be pointed out to the Surveyors that in future similar cases they should state their recommendation regarding the class of the vessel for the information of the Committee.

Lloyd's Register
Foundation

009743-009756-0183