

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME STEEL T.S.S. "WEXFORD"

Report Gls.

No. 39291

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

When due _____

❖ A.1. (steel) "For Government Service"

2 Dks (steel)

Cell DB 12' 16t. DTf 18' 24t. DTa 16' 36t. FPT 5t. APT 20t.

FK. 11BH. 1st. cem. Lloyds A.Y.C.P.



© 2021

Lloyd's Register
Foundation

M *AES*

15-11-19

Gls 24/11/1919.

It is concluded, the Water Ballast Tanks have been tested as required by the Rules, but the Surveyors should be requested to state if this is so.

009757-009770-0042