

7 - MAR 1933

Sent to Chief Surveyors.

Received from Chief Surveyors

VESSEL'S NAME Steel Sc. tug "ST. FAITH" Report Lon. No. 98434A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24.5.92.

Nature of Survey

When due

The class is subject to the starboard oil fuel tank not being used until repaired.

The Vancouver Surveyors now forward a letter from the Owners reading as follows:-

"Commencing this date, kindly take our tug "ST. FAITH" from Lloyd's Register, as we desire to discontinue this registration".

It is submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class
Insert ...



© 2021
Lloyd's Register
Foundation

009780-009788-0170