

COPY

Supplementary Specification after
examination of Tail Shaft May 12th.
Tug "ST. FAITH".

Tail Shaft:

A new tail shaft of approved and tested material with continuous liner to be supplied and fitted. Vessel to be re-docked for this purpose.

Separate price.

Steering Engine:

Engine to be lifted, keyway on steering gear shaft to be re-cut and new key fitted.

Side slack in main bearings to be taken up.

Separate price.

(Sgd) F.L. Kurtz.
Owners' Representative.

(Sgd) Charles Clarkson.
Underwriters' Surveyor.

BURRARD DRY DOCK CO. LTD.
(Sgd) H.A. Wallace.
Contractor.

(Sgd) A. Scott.
Classification Surveyor.

May 12th, 1931.



© 2021

Lloyd's Register
Foundation