

1,9,24.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. s.s. "ST. FAITH".

Rpt.

Ver.

No1672 ~~8~~.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The class of this vessel was expunged with a red line in March last.

The Vancouver Surveyor now reports that with a view to reinstatement of class the vessel has been placed in dry dock and the requirements of a s.s. No.2 carried out.

The bottom has been cleaned and coated and minor repairs effected.

The side and cross bunkers have been done away with and oil fuel tanks have been placed on board, built in accordance with approved plans.

It is submitted the vessel appears worthy to have her original class reinstated with record of survey 8-26 and notation of s.s. Ver. No.2-26.

A.1 For Towing Purposes.

8-26 Ver.

s.s. Ver. No.2-26.

Insert Lloyd's A. & T.P.



14.9.26.

Lloyd's Register
Foundation

009780-009788-0194

Filled to 150° 8 26 27 above 150° 2