

EA

15 FEB 1963

Ship's name

"DIRECTOR MADARIAGA"

Port

ROT.

No. 55137

The class of this ship *100A1 was withdrawn from the Register Book in March 1959 at the Owners request.

Reclassification with the Society is now desired.

The ROTTERDAM Surveyors report (12,62) this ship afloat and a number of tanks and other items examined but not for Special Survey. The examination of the tanks disclosed the fact that repairs are required to cracked stringers also to centre girder.

It is considered that as the Reclassification Special Survey has not commenced the ship is not eligible to have a Notation of "Reclassification Contemplated" inserted in the Register Book.

IT IS SUBMITTED ACTION be DEFERRED pending further information.

IN S.R.L. APPENDIX

No.4 keel plate, A.3 (p & s)
and B.3 (s.s.) set in.

Rmt

*ABM.
21-1-63*



© 2021

Lloyd's Register
Foundation