

LONDON COPY.

LLOYD'S REGISTER OF SHIPPING



BUENOS AIRES REPORT N°

29857-

Port BUENOS AIRES

8th. December, 1958.-

This is to Certify *that I have*

Surveyed the Machinery of the T.M.Tanker "DIRECTOR MADARIAGA",

11633 tons gross of Buenos Aires, on 17th. November, 1958,
whilst the vessel lay afloat at La Plata, for water tube
donkey boiler(exhaust gas)survey, and engine defects,

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book

W.T. DBS 10,58 as previously recommended, when the safety
valves of the port and starboard boilers have been satisfactorily
adjusted
and that her Machinery Classification Record be continued in the Book.

subject to fractures in port and starboard main engine bedplates
being re-examined before the end of 11,59(12 months).-

Parts now examined:

(C.S. Items only)
xxxxxxxxxxxxxx

To complete the W.T. DBS, a statement is required, signed
by the Chief Engineer, covering the satisfactory adjustment of the
port and starboard water tube donkey boilers(exhaust gas).-

James S. Cook.

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, of the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.)

009780-009788-0263