

in the case of this vessel, and it is considered that

"DIRECTOR MADARIAGA"

The class is subject to the lighting fittings in the bridge 'tween deck being replaced by approved fittings before the end of 12.51.

Correspondence has since taken place on this matter, and in endorsement of 5. 1. 51, it was agreed that the case would be met if the rubber bushes in the cable glands be replaced by lead bushes.

IT IS SUBMITTED the vessel's class be amended to read "SUBJECT TO Rubber bushes in cable glands of lighting fittings in bridge 'tween deck to be replaced by lead bushes at first opportunity". The Surveyors and Owners should be informed accordingly.

End

15. 1. 51.



© 2021

Lloyd's Register  
Foundation

009780-009788-0277