

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



Port NOTTINGHAM.

23rd May, 1957.

This is to Certify that

J.H. Davies & J.B. Taylor,

the undersigned Surveyor to this Society did at the request of
Messrs. Whiteley-Read Engineers Ltd.,
 and subsequently
 attend their Works on the 11th March, 1957/ for the purpose of
 inspecting and testing One M.S. Welded air receivers
 made to the order of Messrs. Crossley Bros. Ltd.,
 and intended for their Order No. 0.74200.

The material has been tested as required by the rules, and the
 scantlings of the air receiver are in accordance with the approved plan.

The ~~Each~~ air receiver was, in the presence of the undersigned, tested by
 hydraulic pressure to 575 lb. per square inch and
 found satisfactory.

PARTICULARS.


RECEIVER NUMBER.	LENGTH.		INTERNAL DIAMETER. IN.	THICKNESS. IN.	TENSILE STRENGTH. TONS PER SQ. IN.	ELONGATION. % IN.....INS.	BENDS. DEGREES.
	FT.	INS.					
1051/8.	5	6.5/8"	2 3/8	7/16	28-32	20 Min.	180
Drg.No. 1051.							

IDENTIFICATION MARK:—

No.	<u>1051/8.</u>
LLOYD'S TEST.	<u>NOT.</u>
	<u>575</u> Lb.
W.P.	<u>350</u> Lb.
	<u>JHD. 2.5.57.</u>

Surveyor to Lloyd's Register.

Fee £ 3 : 0 : 0



This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers Agents of the Society."

of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers of the Society, or in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers of the Society.



Fee £ : : :

No.
 No.
 LLOYD'S TEST
 No.

IDENTIFICATION MARK:-

NUMBER RECEIPTS	LENGTH	DIAMETER	THICKNESS	LENGTH STRENGTH	EXTENSION	DEGREE

FACTS OF CASE

found satisfactory.

hydraulic pressure to 100 lb. per square inch and

Each air receiver was, in the presence of the undersigned, tested by

soundings of the air receiver are in accordance with the approved plan.

The material has been tested as required by the rules, and the

and intended for

made to the order of

inspecting and testing

for the purpose of

of the undersigned Surveyor to this Society did at the request of

This is to Certify that



LLOYD'S REGISTER OF SHIPPING



© 2021 Lloyd's Register Foundation

RECEIPTS

COPIES

Certificate No.

understood that neither the Society nor any Member of any of its Committees is under any obligation to accept responsibility for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers of the Society.