

date of internal examination of the boiler.....
rveyor examine the Safety Valves of the Main Boilers?.....
To what pressure were they afterwards adjusted under steam?

Yes

009789-009795-0174

4E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

8 DEC 1955

NAME "D'IVORA"

REPORT Hfx.

No. 6966

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Survey REPAIRS-TO-ENGINES-AND-BOILERS-DUE-TO-DAMAGE-THROUGH

BS. due 8.55. partly held now.

This vessel is out of commission and laid up (see correspondence)

IT IS SUBMITTED the vessel is eligible to remain AS CLASSED.



Lloyd's Register
Foundation