

STAT.

~~WAV.~~ "BONITA" ^{EX}

S.S. "BONITA" ex "KITTERN"

In reply to the Bergen Surveyor's letter of the 21st instant regarding equipment for the above-named ship, IT IS SUBMITTED he be informed:

1. The Figure '1' for equipment in the ship's Class can be assigned as desired, provided the two bower anchors, stream anchor and 75 fathoms of 1-2/16" diameter chain cable now supplied have been tested as required by the Rules - the particulars to be noted in the appropriate space in his Report, and an additional 15 fathoms of 1-2/16" diameter chain cable ~~be~~ be supplied.
2. From the marks found on the remaining third bower anchor and 105 fathoms of chain cable, it would appear that these items are part of the ship's original equipment, and duplicate Certificates for same will be forwarded in due course.

IT IS FURTHER SUBMITTED that a duplicate of each of the following Certificates be obtained and forwarded to the Bergen Surveyor as requested:-

Certificate No. 44636 L.P.H. - Sunderland, dated 29.10.43, a 14 cwt. Byers' Improved Stockless Anchor, and

Certificate No. 2466, L.P.H. - Netherton, dated 11.11.43, for 150 fathoms of 1 1/8" diameter stud link chain cable, and

Certificate No. 2475, L.P.H. Netherton, dated 12.11.43, for 30 fathoms of 1 1/8" diameter stud link chain cable.

LM
27-8-47.

*Certs
requested
28/8*



© 2021

Lloyd's Register
Foundation

009789-009795-0192