

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex  
Telex No.: 24305

Telephone: ROYal 9166  
17th February, 1960.

lassn. (S)

EJB/HMJ

Dear Sirs,

Tug "JAUNTY"

The Society's Surveyors attended on board this ship between June and November 1959, at Sheerness for the purpose of carrying out the Special and Engine Surveys.

When the Surveyors' report received consideration in this Office a notation of SS 11.59 was assigned to the hull and a notation of ES 11.59 to the machinery and Official Classification Certificates bearing these notations were forwarded to you on the 19th ultimo.

Further examination of the case, however, reveals that the machinery notation was assigned in error in as much as certain work still remained to be done, the outstanding items being as follows:-

Pumping arrangements to be tested.


Electrical installation to be examined under working conditions.

Evaporator safety valves to be adjusted under steam.

Fire extinguishing arrangements to be examined and tested.

Boiler safety valves to be adjusted under steam.

Oil burning installations to be examined under working conditions.



© 2020  
Lloyd's Register  
Foundation  
Cont/.....

009796-009804-0145 1/2



Cont/.....

-2-

17th February, 1960.


Tug "JAUNTY"

This mistake is regretted and in the circumstances I shall be glad if you will be so good as to return the machinery Classification Survey so that this may be issued when the above mentioned survey has been completed under the supervision of the Society's Surveyors.

Yours faithfully,

Deputy Clerk to the  
..Classification Committee.

The Secretary of the Admiralty,  
Naval Store Department,  
WHITEHALL, S.W.1.



© 2020

Lloyd's Register  
Foundation

0145 2 1/2