

COPY

Secretary Marine Board,

The following repairs are necessary to the  
S. S. "Isonomia" before she can be in fit condition  
to proceed to sea.

Leaky rivets in Fore peak tank to be replaced  
or Studded.

Fan Engine repaired.

Steering gear put in order.

Tank and bilge valves and cocks to be made good  
and cause of leak in No 4 hold determined and  
made good.

Vessel to be lightened to load line mark.

1 life boat to be re-placed.

Sgd. A. A. Mc Innes

Surveyor Marine Board.

Kingston, Ja.,

25. 2. 27

Copy to Master.



© 2021

Lloyd's Register  
Foundation

009815 001826-0040