

5c.12.16.

F.E.

Received by Chief Ship Surveyor 30.12.18

Received from Chief Ship Surveyor

VESSEL'S NAME

Shells "Node"

Rpt.

Lon

No. 81398

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

28.5

Depth "d"

8.8

Framing: Table No. 3. page 9.

Description

Single Angle as approved

Longitudinal No.

2451

Proportions

Length =

8.6

Depth =

~~Deck~~ Sheerstrake as approved.

The Anchors & chains supplied by the Admiralty have been tested as required but Certificates have not been produced.

The collective weight of the Anchors is slightly in excess of that approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \star 100 A-1. (Steel) for Fishing purposes.

1 DK

BK $7\frac{1}{2}$ 3BH. Am. Lloyd's exp.

M
31.12.18

The Surveyors should forward the tests of the Anchors & chain cables.



© 2021

Lloyd's Register Foundation

009848-009859-0054