

COPY

LLOYD'S REGISTER OF SHIPPING

Port G O T H E N B U R G .17th July, 1961.This is to Certify *that I have*

Surveyed Part of the Machinery of the Steamer "FERNANDO", 1772 tons
gross, of Barranquilla,

and that I will transmit to the Committee of Lloyd's Register of Shipping, London,
 a Report stating that all recommendations made by me in connection therewith have
 been carried out to my satisfaction; also that I will **Recommend** that in the case of
 this Vessel the following Survey Records be made in the Supplement to the Register Book

MBS 6,61 on completion of the survey

and that her Machinery Classification Record be continued in the Book.

Parts now examined:~~(C.S. Items only)~~

Starboard main boiler throughout with superheater, safety valves and
 mountings.

Safety valves of the starboard boiler and superheater adjusted under
 steam to 160 lbs. per square inch.

Oil burning and steam smothering installations.

To complete the survey:

Port main boiler and superheater to be examined.

Their safety valves to be adjusted under steam.

(B. Fridén)

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

Auxiliary Boiler Survey	SGS	Steam Generator Survey
Continuous Survey of Engines	SPS	Steampipe Survey
Donkey Boiler Survey	TS	Tailshaft Survey
Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
Main Boiler Survey	TSN	Tailshaft renewed
Admitted for oil fuel (date) FP above 150°F.	TS(OG)	Tailshaft Survey—Oil Gland

I upon the terms of the Rules and Regulations of the Society, which provide that:—
 of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
 neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held
 responsible in any report or certificate issued by the Society or its Surveyors, or in any entry in the
 Register of the Society, or for any error of judgment, default or negligency of any of its Committees
 or Surveyors, or other Officers or Agents of the Society."